
Product Change Notice

Reason for Change

This PCN announces the release of Sony SMO F561 optical drive firmware version 1.12. This firmware is available at no cost from Plasmon via the website www.plasmontech.com.

Description of Change

The following changes/features are incorporated into the new firmware release:

- x Improved use with PRIMDISC 5.2GB media.
- x Improved reallocation routine in CWO media.

Firmware


Confirm the current firmware by issuing a SCSI inquiry on the drive.

The following table shows the release history of the Sony SMO F561 optical drive firmware.

Code

To determine the drive revision letter and manufacturing date, see the figure below.

The drive revision letter and manufacturing date are found on a label located on top of the drive as shown in the following picture.



Contact Information for Technical Questions:

Americas and Asia Pacific

Plasmon Technical Support Team
United States Calls: 1-877-585-6793
International Calls: 1-719-593-4437
Fax: 1-719-593-4192
Email: tech.support@plasmon.com
Internet: www.plasmon.com

Europe, Africa, and Middle East

Plasmon Technical Support Team
International Calls: +44 (0) 1763 262 963
Fax: +44 (0) 1763 264 407
Email: support@plasmon.co.uk
Internet: www.plasmon.com